

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**GJ950**  
**North**  
**> 1**  
**1.265 mi.**  
**6681 ft.**  
**90 AVE I/BKLYN**  
**90 AVENUE T**  
**NEW YORK CITY, NY**  
**Site 2 of 2 in cluster GJ**

**NY Spills** **S102146201**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**13 ft.**

**SPILLS:**

Name: 90 AVE I/BKLYN  
Address: 90 AVENUE T  
City,State,Zip: NEW YORK CITY, NY  
Spill Number/Closed Date: 9012193 / 1991-02-22  
Facility ID: 9012193  
Facility Type: ER  
DER Facility ID: 100885  
Site ID: 115841  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 1991-02-22  
Investigator: TOMASELLO  
Referred To: Not reported  
Reported to Dept: 1991-02-22  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Responsible Party  
Cleanup Ceased: 1991-02-22  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1991-03-15  
Spill Record Last Update: 2004-09-30  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: ""  
Remarks: "TANK SPRING LEAK,SORBENTS USED TO CLEAN UP,WILL REPAIR."

**All Materials:**

Site ID: 115841  
Operable Unit ID: 952006  
Operable Unit: 01  
Material ID: 428696  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 3.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported